



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Supervisor DR7

Inspection Report
Minerals Regulatory Program
Report Date: June 27, 2005

Mine Name: Apex Mine
Operator or Permittee Name:
Tech Cominco American, Inc.
Inspector(s): Doug Jensen

Permit number: M/053/004
Inspection Date: June 21, 2005
Inspection Start Time: 4:30PM
Inspection End Time: 5:00 PM

Other Participants: None

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
While in the area, checked the site.

Directions to the site:
See previous inspection memos.

Inspection Summary:
The gate into the site was locked. Walked into the site to check the stability of the site. I could not see any concerns at the portal and shop area. The area is kept clean and there were no environmental problems evident. The site remains inactive, no changes.

Inspection Date: June 21, 2005; Report Date: June 27, 2005

Page 2 of 2

M/053/004

Conclusions/Recommendations:

Tech Cominco wishes to leave this site on an inactive status. I will continue to inspect when I am in the area.

Inspector's Signature

A handwritten signature in cursive script, appearing to read "Doug Jensen", written over a horizontal line.

Date: June 27, 2005

DJ:jb

cc: Tech Cominco American, Inc, Operator

O:\M053-Washington\M0530004-ApexMine\Final\06212005insp.doc